

USB Arc Flexible Lighter

1.For lighting Candle, Solid Alcohol, cigarette, Incense, Gas Stove ,Wood Wool and etc.

2.Feature:

2.1: Environmentally-Friendly.

2.2: Clean

2.3: Rechargeable

2.4: Convenient USB connect

2.5: Low-Carbon Electricity

2.6: Long Lifecycle

2.7: More safety

2.8: Smart Charging Circuit

2.9:Flexible tube can ignite easily

3. Instruction

3.1: Charging through the USB cable by connecting to computers, cell phone chargers and any other chargers with the output voltage of DV 5V \pm 0.5V and output current below 3000MA.

3.2: During charging, the indicator light at the left side of the product will be turned on. The light will be turned off automatically after full charge.

3.3: A charge can be filled within 0.5-1h. Be sure disconnecting the power immediately after fully charged. Overcharging will shorten battery life.

3.4: The battery is rechargeable. Before the battery is fully discharged, immediate charges after use will extend battery life.

3.5: After charging, forward the switch of the bonnet, then press down the button to cause the arc spark to ignite. Use to light less than 10 seconds per time.


3.6: During the ignition, there will be noise of "zee, zee", which is high-voltage power generation, please use with release.

3.7: After using, Please backward the bonnet in the initial position.

WARNING

WARNING: KEEP OUT OF REACH OF CHILDREN. Failure to follow instructions may result in burn injury.

- Do not use a sharp object to pierce or burn this product;
- Do not touch the electric spark, for there is the risk of high temperature and voltage.
- Do not place the product into water or other liquids into moisture status, or it will cause a short circuit.
- Do not use this product on any chargers other than the chargeable chargers mentioned above!
- Do not lit for more than 10 seconds, in order to avoid the high temperature to burn the skin and affect product life;
- Ignite Arc Lighter away from face, skin, clothing and combustible substances.
- Be sure the arc flame has been fully extinguished after use.
- Never expose to temperature from sun or otherwise more than 120°F(49°C). Avoid prolonged sun exposure, especially in a glass case or in a car.
- Never puncture or put in fire. Do not place near flame or sparks.
- Do not leave the fully charged battery connected to a power source.



MADE IN CHINA